

In the Specification

On page 5, amend the paragraphs which appear on lines 8 – 13 of page 5 with the following new paragraphs:

Fig. 6 is a view like Figs. 4 and 5, but showing the end portions of the channel member bent downwardly around the broken lines that are shown by Fig. 5; and

Fig. 7 is a side elevational view showing the insert of Fig. 6 positioned within the upper channel member, and showing the upper end portion of the stud in the process of being moved upwardly into a socket that is formed by and between the two end portions of the clip and by and between the flanges of the upper channel member; and

Fig. 8 is a view like Fig. 7, but showing the upper end portion of the stud moved upwardly into the socket formed by the end portions of the clip.